



NOTES:
 1. BACKFILL AROUND THE CULVERTS SHALL BE CEMENT STABILISED MATERIAL IT SHALL BE FULL DEPTH OF THE EMBANKMENT AND EXTEND TO THE OUTER EDGES OF THE WINGWALLS.

TYPICAL PLAN
 (BASE SLAB REINFORCEMENT AND BARRELS NOT SHOWN)
 NTS

Bridge No: 3078
 Bridge Replacement
 Ballaying Road
 Shire of Wagin